CARFAX

Vehicle History Report #: 53287861
Report Date: May 11, 2024 | 6:52 PM EDT
Report Status: Complete

2013 FORD EXPLORER XLT

Sport utility vehicle | 6 Cylinders | Gas
1FM5K8D83DGA19116
Country of Assembly: United States
Last Reported Odometer: n/a



Accident/Damage Records Found



Last Registered In:
Ontario (Normal)

2 Service Records Found



No U.S. History Found



3 Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.
Visit us at **support.carfax.ca**

This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of May 11, 2024 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

1FM5K8D83DGA19116

CamScanner

Vehicle History Report

Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
2020 Mar 2	**Ontario, Canada**	
	Claim: Other Damage	$8,273.00

Registration

This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: *Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.*

Service Records

DATE	ODOMETER	SOURCE	DETAILS
2015 Jun 2		Krown Concord Vaughan, Ontario, Canada	**Vehicle serviced** • Undercoating/rustproofing applied
2021 Nov 8		Service Facility	**Vehicle serviced** • Inspection performed • Alignment checked

Open Recalls

Recall #: 24S02 | EXTERIOR A PILLAR APPLIQUE INSPECTION Recall Date: 2024 Jan 23

Recall Description

IN SOME OF THE AFFECTED VEHICLES IT MAY BE POSSIBLE THAT SOME OF THE EXTERIOR A-PILLAR APPLIQUE TRIM CLIP ATTACHMENTS ARE NOT PROPERLY ENGAGED DUE TO IMPROPER ASSEMBLY OR REPAIR. IF THIS OCCURS, THE A-PILLAR APPLIQUE TRIM, WHICH BORDERS THE RIGHT AND LEFT SIDE OF THE WINDSHIELD, MAY BE LOOSE, MISSING OR BECOME DETACHED.

Remedy

FORD MOTOR COMPANY IS WORKING CLOSELY WITH ITS SUPPLIERS TO PRODUCE PARTS FOR THIS REPAIR. WHEN PARTS BECOME AVAILABLE, FORD MOTOR COMPANY WILL NOTIFY YOU VIA MAIL TO SCHEDULE A SERVICE APPOINTMENT WITH YOUR DEALER FOR REPAIRS TO BE COMPLETED FREE OF CHARGE PARTS AND LABOR. PARTS ARE ANTICIPATED TO BE AVAILABLE TOWARD THE LATTER HALF OF 2024.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact FORD or visit Ford's website.

1FM5K8D83DGA19116

CamScanner

Recall #: 21S43 | REAR TOE LINK INSPECTION REPLACEMENT Recall Date: 2021 Nov 24

Recall Description

VEHICLES EXPOSED TO A CORROSIVE ENVIRONMENT WHERE ROAD SALT IS USED EXTENSIVELY DURING WINTER MONTHS, COULD EXPERIENCE A SEIZED REAR SUSPENSION TOE LINK BALL JOINT RESULTING IN A FRACTURED REAR SUSPENSION TOE LINK. WHILE YOUR VEHICLE WAS NOT ORIGINALLY BUILT WITH REAR TOE LINK BALL JOINTS SUSCEPTIBLE TO THIS CONDITION, OUR RECORDS INDICATE THAT SUSCEPTIBLE COMPONENTS WERE SUBSEQUENTLY INSTALLED ON YOUR VEHICLE DURING REAR SUSPENSION SERVICE.

Remedy

FORD MOTOR COMPANY HAS AUTHORIZED YOUR DEALER TO INSPECT BOTH TOE LINK CONNECTIONS TO CONFIRM THAT A SUSCEPTIBLE BALL JOINT WAS INSTALLED. IF YOUR VEHICLE HAS A SUSCEPTIBLE BALL JOINT INSTALLED THEN YOUR DEALER WILL REPLACE BOTH REAR TOE LINKS WITH AN UPDATED DESIGN. THESE SERVICES MUST BE PERFORMED ON ALL AFFECTED VEHICLES AT NO CHARGE TO THE VEHICLE OWNER.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact FORD or visit Ford's website.

Recall #: 19S17 | REAR SUSPENSION TOE LINK REPLACEMENT Recall Date: 2022 Feb 17

Recall Description

ON YOUR VEHICLE, FREQUENT FULL ARTICULATION OF THE REAR SUSPENSION MAY INCREASE THE STRESS ON THE REAR SUSPENSION TOE LINK, WHICH MAY, OVER TIME, RESULT IN A TOE LINK FRACTURE.

Remedy

FORD MOTOR COMPANY HAS AUTHORIZED YOUR DEALER TO REPLACE YOUR REAR SUSPENSION TOE LINKS FREE OF CHARGE PARTS AND LABOR.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact FORD or visit Ford's website.

Stolen Vehicle Check

This vehicle is not actively declared stolen.

Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2012 Apr 20		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Vehicle colour noted as black
2012 Nov 8		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2014 Feb 3		Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed

1FM5K8D83DGA19116

CamScanner

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
		Ontario, Canada		
2014 Dec 29		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2015 Jan 28		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal Vehicle colour noted as black
2015 Jun 2		Krown Concord Vaughan, Ontario, Canada	Service Record	Vehicle serviced
2016 Sep 9		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2018 Sep 9		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2020 Mar 2		Insurance Records Ontario, Canada		
2020 Sep 24		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2021 Nov 8		Service Facility	Service Record	Vehicle serviced
2021 Nov 24		FORD	Recall	Manufacturer Recall Issued Recall # 21S43
2022 Feb 17		FORD	Recall	Manufacturer Recall Issued Recall # 19S17
2022 Sep 23		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as black
2023 Dec 15		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as black
2024 Jan 23		FORD	Recall	Manufacturer Recall Issued Recall # 24S02

1FM5K8D83DGA19116

CamScanner