



Vehicle History Report # 70586052
Report Date: June 15, 2026 | 10:17 a.m. EDT
Report Status: Complete

2021 RAM PROMASTER 3500 3500 HIGH

Van cargo | 6 Cylinders | Flexible
3C6MRVJG6ME564465
Country of Assembly: Mexico
Last Reported Odometer: 58,253 KM



No Accident/Damage Records Found



Last Registered In:
Québec (Normal)



17 Service Records Found



No U.S. History Found



3 Open Recalls Found



Not Actively Declared Stolen



No Import/Export Records Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of June 15, 2026 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

✓ There are no accidents/damage reported on this vehicle.



Registration

✓ This vehicle has been registered in the province of **Québec** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2021 Nov 1		Excellence Dodge Chrysler Saint-Eustache, Québec, Canada	Vehicle serviced Tire(s) replaced
2022 Mar 7	3,557 KM	NAPA AUTOPRO Alex Pneu Mecanique Mario Bedard Montral, Québec, Canada	Vehicle serviced - Oil and filter changed - Tires rotated - Vehicle washed/detailed
2022 Apr 26	5,061 KM	NAPA AUTOPRO Alex Pneu Mecanique Mario Bedard Montral, Québec, Canada	Vehicle serviced
2022 Sep 23	10,363 KM	NAPA AUTOPRO Alex Pneu Mecanique Mario Bedard Montral, Québec, Canada	Vehicle serviced - Oil and filter changed - Vehicle washed/detailed
2022 Nov 30	13,961 KM	NAPA AUTOPRO Alex Pneu Mecanique Mario Bedard Montral, Québec, Canada	Vehicle serviced
2022 Dec 14	14,869 KM	NAPA AUTOPRO Alex Pneu Mecanique Mario Bedard Montral, Québec, Canada	Vehicle serviced
2023 Mar 6	19,034 KM	NAPA AUTOPRO Alex Pneu Mecanique Mario Bedard Montral, Québec, Canada	Vehicle serviced - Oil and filter changed - Tires rotated - Vehicle washed/detailed
2023 May 18	21,366 KM	NAPA AUTOPRO Alex Pneu Mecanique Mario Bedard Montral, Québec, Canada	Vehicle serviced

ODOMETER		SOURCE	DETAILS
2023 Sep 8	28,104 KM	NAPA AUTOPRO Alex Pneu Mecanique Mario Bedard Montral, Québec, Canada	Vehicle serviced - Cabin air filter replaced/cleaned - Oil and filter changed - Tires rotated - Vehicle washed/detailed
2023 Nov 2	31,199 KM	NAPA AUTOPRO Alex Pneu Mecanique Mario Bedard Montral, Québec, Canada	Vehicle serviced
2024 Feb 2	36,611 KM	NAPA AUTOPRO Alex Pneu Mecanique Mario Bedard Montral, Québec, Canada	Vehicle serviced - Oil and filter changed - Tires rotated - Vehicle washed/detailed
2024 Jul 3	44,139 KM	Longue Pointe Chrysler Dodge Ram Jeep Fiat Saint-Leonard, Québec, Canada	Vehicle serviced
2024 Sep 11	47,445 KM	Chartrand Ford Ventes Inc. Duvernay Laval, Québec, Canada	Vehicle serviced
2024 Nov 18	51,047 KM	Longue Pointe Chrysler Dodge Ram Jeep Fiat Saint-Leonard, Québec, Canada	Vehicle serviced Back-up camera replaced
2025 Feb 24	58,253 KM	Champlain Dodge Chrysler Verdun, Québec, Canada	Vehicle serviced - Ball joint(s) replaced - Starter replaced
2025 Apr 23		Champlain Dodge Chrysler Verdun, Québec, Canada	Vehicle serviced
2026 Mar 26		Champlain Dodge Chrysler Verdun, Québec, Canada	Vehicle serviced



Open Recalls

Recall #: 21B | 2021-2022 VF - Flashers and Turn Signals Recall Date: 2024 Mar 21

Recall Description

Federal Motor Vehicle Safety Standard ("FMVSS") 108 Table I-a requires Turn Signal Lamps to "Flash when the turn signal flasher is actuated ..." and the Taillamps "Must be activated when the headlamps are activated." Suspect vehicles may not have functioning taillamps/turn signal lamps.

Remedy

FCA US will conduct a voluntary safety recall on all affected vehicles. The remedy is under development.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact RAM or visit [Ram's website](https://www.mopar.com/en-ca/my-vehicle/recalls/search.html). (<https://www.mopar.com/en-ca/my-vehicle/recalls/search.html>)

Recall #: 59C | 2019-2020 JC & 2019-2021 VF Rearview Camera Loss o Recall Date: 2025 Sep 03

Recall Description

Federal Motor Vehicle Safety Standard (FMVSS) No. 571.111 S6.2.6 requires that "The rear visibility system default to the rearview image being visible and meet the requirements of FMVSS No. 571.111 S6.2.1 (field of view) and S6.2.2 (image size) at the beginning of each backing event, regardless of any modifications to the field of view that the driver had previously selected..." Suspect vehicles may not display the rearview image during a backing event under certain conditions.

Remedy

FCA US will conduct a voluntary safety recall for all affected vehicles to replace the rearview camera.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact RAM or visit [Ram's website](https://www.mopar.com/en-ca/my-vehicle/recalls/search.html). (https://www.mopar.com/en-ca/my-vehicle/recalls/search.html)

Recall #: B3C | 2018-2025 VF Engine Compartment Fire - High Duty C Recall Date: 2025 Nov 25

Recall Description

Some 2018-2026MY Ram ProMaster vehicles built for fleet sale may have been assembled with a cooling fan module which is susceptible to premature bearing wear and inadequate fuse protection. Certain extremely demanding fleet duty cycles can cause premature bearing wear resulting in high current draw combined with inadequate fuse protection on the 400W fan circuit which may lead to a vehicle fire.

Remedy

FCA US will conduct a voluntary safety recall on all affected vehicles to replace the cooling fan module and a fuse, and provide an owner's manual addendum and label for the Power Distribution Center (PDC).

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact RAM or visit [Ram's website](https://www.mopar.com/en-ca/my-vehicle/recalls/search.html). (https://www.mopar.com/en-ca/my-vehicle/recalls/search.html)



Stolen Vehicle Check

✔ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2021 Nov 1		Excellence Dodge Chrysler Saint-Eustache, Québec, Canada	Service Record	Vehicle serviced
2021 Nov 3		Motor Vehicle Dept. Québec, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2022 Mar 7	3,557 KM	NAPA AUTOPRO Alex Pneu Mecanique Mario Bedard Montral, Québec, Canada	Service Record	Vehicle serviced
2022 Mar 23		Motor Vehicle Dept. Québec, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2022 Apr 26	5,061 KM	NAPA AUTOPRO Alex Pneu Mecanique Mario Bedard Montral, Québec, Canada	Service Record	Vehicle serviced
2022 Sep 23	10,363 KM	NAPA AUTOPRO Alex Pneu Mecanique Mario Bedard Montral, Québec, Canada	Service Record	Vehicle serviced
2022 Nov 30	13,961 KM	NAPA AUTOPRO Alex Pneu Mecanique Mario Bedard Montral, Québec, Canada	Service Record	Vehicle serviced
2022 Dec 14	14,869 KM	NAPA AUTOPRO Alex Pneu Mecanique Mario Bedard Montral, Québec, Canada	Service Record	Vehicle serviced
2023 Mar 6	19,034 KM	NAPA AUTOPRO Alex Pneu Mecanique Mario Bedard Montral, Québec, Canada	Service Record	Vehicle serviced
2023 May 18	21,366 KM	NAPA AUTOPRO Alex Pneu Mecanique Mario Bedard Montral, Québec, Canada	Service Record	Vehicle serviced
2023 Sep 8	28,104 KM	NAPA AUTOPRO Alex Pneu Mecanique Mario Bedard Montral, Québec, Canada	Service Record	Vehicle serviced
2023 Nov 2	31,199 KM	NAPA AUTOPRO Alex Pneu Mecanique Mario Bedard Montral, Québec, Canada	Service Record	Vehicle serviced
2024 Jan 19		Motor Vehicle Dept. Québec, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2024 Feb 2	36,611 KM	NAPA AUTOPRO Alex Pneu Mecanique Mario Bedard Montral, Québec, Canada	Service Record	Vehicle serviced
2024 Mar 21		RAM	Recall	Manufacturer Recall Issued Recall # 21B
2024 Apr 1		Motor Vehicle Dept. Québec, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2024 Jul 3	44,139 KM	Longue Pointe Chrysler Dodge Ram Jeep Fiat Saint-Leonard, Québec, Canada	Service Record	Vehicle serviced

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2024 Sep 11	47,445 KM	Chartrand Ford Ventes Inc. Duvernay Laval, Québec, Canada	Service Record	Vehicle serviced
2024 Nov 18	51,047 KM	Longue Pointe Chrysler Dodge Ram Jeep Fiat Saint-Leonard, Québec, Canada	Service Record	Vehicle serviced
2025 Feb 24	58,253 KM	Champlain Dodge Chrysler Verdun, Québec, Canada	Service Record	Vehicle serviced
2025 Apr 1		Motor Vehicle Dept. Québec, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2025 Apr 23		Champlain Dodge Chrysler Verdun, Québec, Canada	Service Record	Vehicle serviced
2025 Sep 3		RAM	Recall	Manufacturer Recall Issued Recall # 59C
2025 Nov 25		RAM	Recall	Manufacturer Recall Issued Recall # B3C
2026 Mar 26		Champlain Dodge Chrysler Verdun, Québec, Canada	Service Record	Vehicle serviced
2026 Apr 1		Motor Vehicle Dept. Québec, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial



Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2026 CARFAX Canada ULC. All rights reserved.



3C6MRVJG6ME564465