



Vehicle History Report # 70605493
Report Date: June 15, 2026 | 4:36 p.m. EDT
Report Status: Complete

2017 VOLKSWAGEN GOLF S

Hatchback | 4 Cylinders | Gas
3VW117AU6HM050063
Country of Assembly: Mexico
Last Reported Odometer: 124,570 KM



No Accident/Damage Records Found



Last Registered In:
Ontario (Normal)



15 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import/Export Records Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of June 15, 2026 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

✓ There are no accidents/damage reported on this vehicle.



Registration

✓ This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2017 Dec 21	18,726 KM	Jiffy Lube # 3496 Brampton, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Fluids checked - Oil and filter changed
2018 Aug 16	26,314 KM	Barrie Volkswagen Barrie, Ontario, Canada	Vehicle serviced - Four wheel alignment performed - Wheel bearings checked - Wheel bearing(s)/hub(s) replaced
2018 Nov 28	33,795 KM	Milton Volkswagen Milton, Ontario, Canada	Vehicle serviced Vehicle washed/detailed
2019 Oct 3	40,451 KM	ORILLIA VOLKSWAGEN Orillia, Ontario, Canada	Vehicle serviced - Engine/powertrain computer/module checked - Intake manifold gasket(s) replaced
2020 Feb 6	44,188 KM	ORILLIA VOLKSWAGEN Orillia, Ontario, Canada	Vehicle serviced - Camshaft(s) replaced/repared - Engine/powertrain computer/module checked - Valve lifters replaced
2020 Feb 26	44,204 KM	ORILLIA VOLKSWAGEN Orillia, Ontario, Canada	Vehicle serviced
2021 Sep 29	64,472 KM	Two Guys Auto Service Bracebridge, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Fluids checked - Oil and filter changed
2021 Nov 29	68,709 KM	Two Guys Auto Service Bracebridge, Ontario, Canada	Vehicle serviced Tire(s) changed

3VW117AU6HM050063

ODOMETER		SOURCE	DETAILS
2022 Apr 26	71,833 KM	Two Guys Auto Service Bracebridge, Ontario, Canada	Vehicle serviced • Brakes checked • Brake rotor(s) replaced • Fluids checked • Front brake pads replaced • Front brake rotor(s) replaced • Oil and filter changed • Rear brake pads replaced • Rear brake rotor(s) replaced • Tire(s) balanced
2023 May 6	87,315 KM	The Rocky Island Tire Company Bracebridge, Ontario, Canada	Vehicle serviced • Tire(s) changed
2023 Nov 27	94,346 KM	Bracebridge Radiator & Muffler Bracebridge, Ontario, Canada	Vehicle serviced • Headlight bulb(s) replaced • Oil and filter changed
2023 Dec 30	94,914 KM	The Rocky Island Tire Company Bracebridge, Ontario, Canada	Vehicle serviced • One tire balanced • One tire mounted
2024 Jun 19	101,553 KM	Take 5 Oil Change Bracebridge, Ontario, Canada	Vehicle serviced • Oil and filter changed
2025 Nov 6	119,764 KM	Bracebridge Radiator & Muffler Bracebridge, Ontario, Canada	Vehicle serviced • Brakes checked • Brake fluid flushed/changed • Oil and filter changed • Rear brake caliper(s) replaced • Tire(s) replaced
2026 Apr 22	124,570 KM	Ajax Mitsubishi Ajax, Ontario, Canada	Vehicle serviced



Open Recalls

Recall #: 20UF | SUCTION JET PUMP Recall Date: 2024 Feb 16

Recall Description

The suction jet pump inside the fuel tank is designed to purge fuel from the Evaporative Emissions (EVAP) system. If a specific seal inside an affected suction jet pump fails, the fuel may flow directly into the EVAP system. If this happens, fuel could accumulate in the EVAP system and may leak through the charcoal canister filter element. Leaking fuel, in the presence of an ignition source, may result in a fire.

Remedy

Replace the suction jet pump.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit [Volkswagen's website](https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html). (https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html)

3VW117AU6GHM050063



Stolen Vehicle Check

✓ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2017 Aug 31		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Vehicle colour noted as black
2017 Dec 21	18,726 KM	Jiffy Lube # 3496 Brampton, Ontario, Canada	Service Record	Vehicle serviced
2018 Jul 9	26,153 KM	Auto Auction	Auction Announcement	Vehicle sold Listed as a fleet/lease vehicle
2018 Aug 16	26,314 KM	Barrie Volkswagen Barrie, Ontario, Canada	Service Record	Vehicle serviced
2018 Aug 28		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal
2018 Nov 28	33,795 KM	Milton Volkswagen Milton, Ontario, Canada	Service Record	Vehicle serviced
2019 Jul 4		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2019 Aug 30	40,000 KM	Independent Source Muskoka, Canada	Odometer reading	
2019 Aug 30		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal Vehicle colour noted as black
2019 Oct 3	40,451 KM	ORILLIA VOLKSWAGEN Orillia, Ontario, Canada	Service Record	Vehicle serviced
2020 Feb 6	44,188 KM	ORILLIA VOLKSWAGEN Orillia, Ontario, Canada	Service Record	Vehicle serviced
2020 Feb 26	44,204 KM	ORILLIA VOLKSWAGEN Orillia, Ontario, Canada	Service Record	Vehicle serviced
2020 Oct 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal

3VW117AU6HM050063

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2021 Sep 29	64,472 KM	Two Guys Auto Service Bracebridge, Ontario, Canada	Service Record	Vehicle serviced
2021 Nov 29	68,709 KM	Two Guys Auto Service Bracebridge, Ontario, Canada	Service Record	Vehicle serviced
2022 Apr 26	71,833 KM	Two Guys Auto Service Bracebridge, Ontario, Canada	Service Record	Vehicle serviced
2023 May 6	87,315 KM	The Rocky Island Tire Company Bracebridge, Ontario, Canada	Service Record	Vehicle serviced
2023 Nov 27	94,346 KM	Bracebridge Radiator & Muffler Bracebridge, Ontario, Canada	Service Record	Vehicle serviced
2023 Dec 30	94,914 KM	The Rocky Island Tire Company Bracebridge, Ontario, Canada	Service Record	Vehicle serviced
2024 Feb 16		VOLKSWAGEN	Recall	Manufacturer Recall Issued Recall # 20UF
2024 Jun 19	101,553 KM	Take 5 Oil Change Bracebridge, Ontario, Canada	Service Record	Vehicle serviced
2025 May 21		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2025 Sep 13		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2025 Nov 6	119,764 KM	Bracebridge Radiator & Muffler Bracebridge, Ontario, Canada	Service Record	Vehicle serviced
2026 Apr 7		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as black
2026 Apr 22	124,570 KM	Ajax Mitsubishi Ajax, Ontario, Canada	Service Record	Vehicle serviced



Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

