CARFAX

Vehicle History Report #: 61081017
Report Date: April 29, 2025 | 3:13 p.m. EDT
Report Status: Complete

2011 DODGE GRAND CARAVAN EXPRESS

Van passenger | 6 Cylinders | Flexible
2D4RN4DG2BR652458
Country of Assembly: Canada
Last Reported Odometer: 173,008 KM

No Reported Accidents™



No Accident/Damage Records Found



Last Registered In:
Ontario (Normal)



22 Service Records Found



No U.S. History Found



No Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.
Visit us at **support.carfax.ca**

This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of April 29, 2025 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

2D4RN4DG2BR652458

CamScanner

Vehicle History Report

Accident/Damage

There are no accidents/damage reported on this vehicle.

Registration

This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: *Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.*

Service Records

DATE	ODOMETER	SOURCE	DETAILS
2017 Apr 15	73,138 KM	Active Green & Ross Thornhill, Ontario, Canada	**Vehicle serviced** • Tire repaired
2018 Apr 7	84,297 KM	Great Canadian Oil Change North York, Ontario, Canada	**Vehicle serviced** • Oil and filter changed
2018 Apr 11		Integra Tire And Auto Center Mississauga, Ontario, Canada	**Vehicle serviced** • Maintenance inspection completed • Brake pads replaced • Brake rotor(s) replaced • Front brake pads replaced • Front brake rotor(s) replaced
2018 Jun 12	85,426 KM	Great Canadian Oil Change North York, Ontario, Canada	**Vehicle serviced** • Emissions system serviced
2018 Jul 6	86,093 KM	Integra Tire And Auto Center Mississauga, Ontario, Canada	**Vehicle serviced**
2018 Sep 8	89,140 KM	Great Canadian Oil Change North York, Ontario, Canada	**Vehicle serviced** • Antifreeze/coolant checked • Fuel injection system flushed/serviced • Oil and filter changed
2018 Sep 10	89,294 KM	Integra Tire And Auto Center Mississauga, Ontario, Canada	**Vehicle serviced** • Brakes checked • Rear brake pads replaced
2018 Oct 22	90,416 KM	Integra Tire And Auto Center Mississauga, Ontario, Canada	**Vehicle serviced** • Maintenance inspection completed • Brakes checked • Brake rotor(s) replaced • Chrome/alloy wheels installed • Front brake pads replaced • Front brake rotor(s) replaced • Rear brake pads replaced • Tire(s) changed

2D4RN4DG2BR652458

CamScanner

	ODOMETER	SOURCE	DETAILS
2019 Mar 9	93,941 KM	Great Canadian Oil Change North York, Ontario, Canada	**Vehicle serviced** • Fuel injection system flushed/serviced • Oil and filter changed
2019 Mar 11		Integra Tire And Auto Center Mississauga, Ontario, Canada	**Vehicle serviced** • Maintenance inspection completed • Brake caliper(s) replaced • Front brake pads replaced • Front brake rotor(s) replaced
2019 May 10	95,869 KM	Integra Tire And Auto Center Mississauga, Ontario, Canada	**Vehicle serviced** • Maintenance inspection completed • Tire(s) changed
2019 Jul 19	98,033 KM	Integra Tire And Auto Center Mississauga, Ontario, Canada	**Vehicle serviced** • Spark plug(s) replaced
2019 Sep 15	101,252 KM	Great Canadian Oil Change North York, Ontario, Canada	**Vehicle serviced** • Oil and filter changed
2019 Nov 16	102,853 KM	Integra Tire And Auto Center Mississauga, Ontario, Canada	**Vehicle serviced** • Antifreeze/coolant flushed/changed • Brake caliper(s) replaced • Thermostat replaced • Tire(s) changed
2020 Apr 21	106,049 KM	Integra Tire And Auto Center Mississauga, Ontario, Canada	**Vehicle serviced** • Brakes serviced • Oil and filter changed • Tire(s) changed • Wheel lug stud(s) replaced
2020 Nov 2	112,625 KM	Integra Tire And Auto Center Mississauga, Ontario, Canada	**Vehicle serviced** • Maintenance inspection completed • Oil and filter changed • Tire(s) changed
2021 Jan 13	113,879 KM	Integra Tire And Auto Center Mississauga, Ontario, Canada	**Vehicle serviced** • Maintenance inspection completed • Brake pads replaced • Brake rotor(s) replaced • Rear brake pads replaced
2021 Nov 9	122,226 KM	Integra Tire And Auto Center Mississauga, Ontario, Canada	**Vehicle serviced** • Maintenance inspection completed • Oil and filter changed • Tire(s) changed
2022 Jun 3	129,987 KM	North York Chrysler Jeep Dodge Thornhill, Ontario, Canada	**Vehicle serviced**
2022 Dec 28	139,844 KM	Great Canadian Oil Change North York, Ontario, Canada	**Vehicle serviced** • Maintenance inspection completed • Fluids checked • Oil and filter changed
2024 Jan 13	156,274 KM	Great Canadian Oil Change North York, Ontario, Canada	**Vehicle serviced** • Maintenance inspection completed • Air filter checked • Antifreeze/coolant checked • Fluids checked • Oil and filter changed

2D4RN4DG2BR652458

CamScanner

	ODOMETER	SOURCE	DETAILS
2024 Jul 12	163,648 KM	Great Canadian Oil Change North York, Ontario, Canada	**Vehicle serviced** • Maintenance inspection completed • Fluids checked • Oil and filter changed

Open Recalls

No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact DODGE or visit Dodge's website. (https://www.mopar.com/en-ca/my-vehicle/recalls/search.html)

Stolen Vehicle Check

This vehicle is not actively declared stolen.

Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2011 Apr 18		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Vehicle colour noted as white
2011 Jun 20		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2013 Jun 20		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2015 Jun 20		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2017 Apr 15	73,138 KM	Active Green & Ross Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2017 Jun 20		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2018 Apr 7	84,297 KM	Great Canadian Oil Change North York, Ontario, Canada	Service Record	Vehicle serviced
2018 Apr 11		Integra Tire And Auto Center Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2018 Jun 12	85,426 KM	Great Canadian Oil Change North York, Ontario, Canada	Service Record	Vehicle serviced
2018 Jul 6	86,093 KM	Integra Tire And Auto Center Mississauga, Ontario, Canada	Service Record	Vehicle serviced

2D4RN4DG2BR652458

CamScanner

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2018 Sep 8	89,140 KM	Great Canadian Oil Change North York, Ontario, Canada	Service Record	Vehicle serviced
2018 Sep 10	89,294 KM	Integra Tire And Auto Center Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2018 Oct 22	90,416 KM	Integra Tire And Auto Center Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2019 Mar 9	93,941 KM	Great Canadian Oil Change North York, Ontario, Canada	Service Record	Vehicle serviced
2019 Mar 11		Integra Tire And Auto Center Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2019 May 10	95,869 KM	Integra Tire And Auto Center Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2019 Jul 19	98,033 KM	Integra Tire And Auto Center Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2019 Sep 15	101,252 KM	Great Canadian Oil Change North York, Ontario, Canada	Service Record	Vehicle serviced
2019 Nov 16	102,853 KM	Integra Tire And Auto Center Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2020 Apr 21	106,049 KM	Integra Tire And Auto Center Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2020 Jun 20		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2020 Nov 2	112,625 KM	Integra Tire And Auto Center Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2021 Jan 13	113,879 KM	Integra Tire And Auto Center Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2021 Nov 9	122,226 KM	Integra Tire And Auto Center Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2022 Jun 3	129,987 KM	North York Chrysler Jeep Dodge Thornhill, Ontario, Canada	Service Record	Vehicle serviced
2022 Jun 20		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as white
2022 Dec 28	139,844 KM	Great Canadian Oil Change North York, Ontario, Canada	Service Record	Vehicle serviced
2024 Jan 13	156,274 KM	Great Canadian Oil Change North York, Ontario, Canada	Service Record	Vehicle serviced

2D4RN4DG2BR652458

CamScanner

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2024 Jun 20		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2024 Jul 12	163,648 KM	Great Canadian Oil Change North York, Ontario, Canada	Service Record	Vehicle serviced
2025 Feb 22	173,008 KM	Independent Source Toronto, Ontario, Canada	Odometer reading	
2025 Feb 27		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as white



Questions? We're here to help.

Visit us at **support.carfax.ca**

CARFAX Canada No Reported Accidents™ Badge
The CARFAX Canada No Reported Accidents™ badge is based on the damage records and/or branding information reported to CARFAX Canada. The badge is available for personal vehicles that have only been registered in Canada, and were not, at the time this report was generated, declared stolen.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.
https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use

© 2025 CARFAX Canada ULC. All rights reserved.

CARFAX

2D4RN4DG2BR652458

CamScanner