



Vehicle History Report # 72738361
Report Date: September 15, 2026 | 11:31 a.m. EDT
Report Status: Complete

2014 VOLKSWAGEN JETTA BASE

Sedan | 4 Cylinders | Gas
3VW2K7AJ8EM407536
Country of Assembly: Mexico
Last Reported Odometer: 141,193 KM



Accident/Damage Records Found



Last Registered In:
Ontario (Normal)



12 Service Records Found



U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import/Export Records Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of September 15, 2026 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
2015 Nov 25	Concord, Ontario, Canada	
	Accident Reported: Accident reported: minor damage Vehicle involved in a rear-end collision with another motor vehicle Damage to rear	
	Estimate: Rear Center Estimate Date: 2015 Dec 21	\$1,296.95
	Claim: Unknown	\$1,297.00
2019 Jul 28	Scarborough, Ontario, Canada	
	Accident Reported: Accident reported with another motor vehicle Damage to right side Disabling damage reported	
	Estimate: Total Loss Estimate Date: 2019 Aug 2	\$9,253.49
	Claim: Collision	\$11,315.00



Registration

This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2015 Nov 25		Active Green & Ross Scarborough, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Tire(s) changed
2016 Jan 22	28,320 KM	Volkswagen MidTown Toronto Toronto, Ontario, Canada	Vehicle serviced Maintenance inspection completed

3VW2K7A18EM407536

ODOMETER		SOURCE	DETAILS
2016 May 28	33,655 KM	Active Green & Ross Scarborough, Ontario, Canada	Vehicle serviced - Four tires balanced - Tire(s) balanced - Tire(s) changed
2016 Nov 21	35,438 KM	Active Green & Ross Scarborough, Ontario, Canada	Vehicle serviced Tire(s) changed
2017 Feb 4	41,983 KM	Volkswagen MidTown Toronto Toronto, Ontario, Canada	Vehicle serviced - Fluids checked - Tires rotated
2018 Mar 1		Volkswagen MidTown Toronto Toronto, Ontario, Canada	Vehicle serviced - Air filter replaced - Brakes checked - Brake fluid flushed/changed - Oil and filter changed - Spark plug(s) replaced - Tires rotated
2018 Mar 19		Volkswagen MidTown Toronto Toronto, Ontario, Canada	Vehicle serviced Four tires replaced
2018 May 4		Volkswagen MidTown Toronto Toronto, Ontario, Canada	Vehicle serviced Brakes checked
 2018 Jun 28	64,946 MI	Bergstrom Volkswagen of Oshkosh Oshkosh, Wisconsin, United States	Vehicle serviced One tire mounted
 2018 Sep 4	71,286 MI	Bergstrom Volkswagen of Oshkosh Oshkosh, Wisconsin, United States	Vehicle serviced - Maintenance inspection completed - Drive belts checked - Maintenance reminder reset - Oil and filter changed - Tire condition and pressure checked - Transmission fluid changed - Vehicle washed/detailed
 2019 Apr 18	89,622 MI	Bergstrom Volkswagen of Oshkosh Oshkosh, Wisconsin, United States	Vehicle serviced - Maintenance inspection completed - Alignment checked - Brake fluid flushed/changed - Cabin air filter replaced/cleaned - Oil and filter changed - Spark plug(s) replaced - Tires rotated - Wiper(s) replaced
2025 Jun 5	141,193 KM	Jiffy Lube Etobicoke, Ontario, Canada	Vehicle serviced Oil and filter changed



Open Recalls

Recall #: 37M2 | MICRO SWITCH Recall Date: 2019 Aug 27

Recall Description

Over time, a build up of silicate on the shift lever micro switch contacts can result in an isolation like layer that may be interpreted as an open

micro switch. This open switch normally indicates that the shift lever is in P park position. If the build up happens, it may be possible to remove the key from the ignition switch without the shift lever being in the P park position because the system is unable to recognize that the vehicle is not in P park. This makes the vehicle noncompliant with FMVSS 114 Theft protection and rollaway prevention. If the ignition key is removed without the shift lever being in P Park position, there is a risk that the vehicle may roll away, resulting in a crash that could injure people and damage property.

Remedy
Install an additional switch and circuit board.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit [Volkswagen's website](https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html). (https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html)



Stolen Vehicle Check

✔ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2014 Feb 25		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Vehicle colour noted as white
2014 Nov 17		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2015 Nov 23		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2015 Nov 25		Accident Reported Ontario, Canada	Damage Event	Accident Reported: • minor damage • Vehicle involved in a rear-end collision • with another motor vehicle • Damage to rear
2015 Nov 25		Ontario, Canada	Unknown	
2015 Nov 25		Active Green & Ross Scarborough, Ontario, Canada	Service Record	Vehicle serviced
2015 Dec 21	27,021 KM	Insurance Records Concord, Ontario, Canada	Estimate Repair	Incident Date: 2015-11-25 Rear Center
2016 Jan 22	28,320 KM	Volkswagen MidTown Toronto Toronto, Ontario, Canada	Service Record	Vehicle serviced

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2016 May 28	33,655 KM	Active Green & Ross Scarborough, Ontario, Canada	Service Record	Vehicle serviced
2016 Nov 21	35,438 KM	Active Green & Ross Scarborough, Ontario, Canada	Service Record	Vehicle serviced
2016 Dec 20		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Feb 4	41,983 KM	Volkswagen MidTown Toronto Toronto, Ontario, Canada	Service Record	Vehicle serviced
2017 Nov 17		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Feb 8		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner Reported
2018 Mar 1		Volkswagen MidTown Toronto Toronto, Ontario, Canada	Service Record	Vehicle serviced
2018 Mar 19		Volkswagen MidTown Toronto Toronto, Ontario, Canada	Service Record	Vehicle serviced
2018 Apr 30	54,845 KM	Independent Source Toronto, Ontario, Canada	Odometer reading	
2018 May 2		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal
2018 May 4		Volkswagen MidTown Toronto Toronto, Ontario, Canada	Service Record	Vehicle serviced
 2018 Jun 28	64,946 MI	Bergstrom Volkswagen of Oshkosh Oshkosh, Wisconsin, United States	Service Record	Vehicle serviced
 2018 Sep 4	71,286 MI	Bergstrom Volkswagen of Oshkosh Oshkosh, Wisconsin, United States	Service Record	Vehicle serviced
 2019 Apr 18	89,622 MI	Bergstrom Volkswagen of Oshkosh Oshkosh, Wisconsin, United States	Service Record	Vehicle serviced
2019 Jun 21		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2019 Jul 28		Accident Reported	Damage Event	Accident Reported: • with another motor vehicle • Damage to right side • Disabling damage reported

3VW2K7A18EM407536

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2019 Jul 28		Ontario, Canada	Collision	
2019 Aug 2	111,489 KM	Insurance Records Scarborough, Ontario, Canada	Estimate Repair	Incident Date: 2019-07-28 Total Loss
2019 Aug 27		VOLKSWAGEN	Recall	Manufacturer Recall Issued Recall # 37M2
2019 Nov 22		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as white
2020 Dec 3		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as white
2021 Nov 11		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as white
2023 Mar 17		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as white
2024 Nov 11		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2025 Jun 5	141,193 KM	Jiffy Lube Etobicoke, Ontario, Canada	Service Record	Vehicle serviced
2025 Nov 11		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal



Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

3VW2K7A18EM407536