



Vehicle History Report # 72393364
Report Date: August 31, 2026 | 12:46 p.m. EDT
Report Status: Complete

2019 FORD TRANSIT T-150

Van cargo | 6 Cylinders | Gas
1FTYE1YM1KKB52846
Country of Assembly: United States
Last Reported Odometer: 69,495 KM



No Accident/Damage Records Found



Last Registered In:
Ontario (Normal)



21 Service Records Found



No U.S. History Found



No Open Recalls Found



Not Actively Declared Stolen



No Import/Export Records Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of August 31, 2026 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

✓ There are no accidents/damage reported on this vehicle.



Registration

✓ This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: *Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.*



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2019 Nov 19		Krown Rust Control Burlington, Ontario, Canada	Vehicle serviced Undercoating/rustproofing applied
2019 Nov 22		Service Facility Canada	Vehicle serviced
2019 Nov 25		Whiteoak Ford Lincoln Mississauga, Ontario, Canada	Vehicle serviced Pre-delivery inspection completed
2019 Dec 2		Whiteoak Ford Lincoln Mississauga, Ontario, Canada	Vehicle serviced
2021 Sep 15	63,830 KM	Active Green & Ross Markham, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tire repaired
2021 Dec 7	74,920 KM	Active Green & Ross Markham, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Four tires balanced - Four tires mounted - Oil and filter changed - Tire condition and pressure checked - Tire(s) balanced - Tire(s) changed - Tire(s) replaced
2022 Mar 14	85,609 KM	Active Green & Ross Markham, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Brakes checked - Brake calipers cleaned/serviced - Brake rotor(s) replaced - Brakes serviced - Front brake pads replaced

ODOMETER		SOURCE	DETAILS
			• Front brake rotor(s) replaced • Oil and filter changed • Rear brake pads replaced • Rear brake rotor(s) replaced
2022 Jun 21	96,823 KM	Active Green & Ross Markham, Ontario, Canada	Vehicle serviced • Maintenance inspection completed • Oil and filter changed
2022 Sep 26	109,386 KM	Jiffy Lube #1094 Burlington, Ontario, Canada	Vehicle serviced • Maintenance inspection completed • Fluids checked • Oil and filter changed
2023 Jan 9	124,974 KM	Active Green & Ross Markham, Ontario, Canada	Vehicle serviced • Maintenance inspection completed • Oil and filter changed
2023 Mar 21	136,973 KM	Active Green & Ross Markham, Ontario, Canada	Vehicle serviced • Maintenance inspection completed • Oil and filter changed
2023 Nov 22	170,813 KM	Active Green & Ross Markham, Ontario, Canada	Vehicle serviced • Maintenance inspection completed • Oil and filter changed • Tires rotated
2024 Jul 17	194,808 KM	Active Green & Ross Markham, Ontario, Canada	Vehicle serviced • Alternator replaced • Antifreeze/coolant checked • Brakes checked • Brake rotor(s) replaced • Cooling system checked • Cooling system serviced • Drive belt(s) replaced • Front brake pads replaced • Front brake rotor(s) replaced • Oil and filter changed • Serpentine belt replaced • Tire condition and pressure checked • Tire repaired • Tire(s) balanced
2024 Sep 12	200,407 KM	Service Facility	Vehicle serviced • Brakes checked • Brake rotor(s) replaced • Cabin air filter replaced/cleaned • Differential cover resealed • Differential fluid flushed/changed • Differential serviced • Light bulb(s) replaced • Oil and filter changed • Rear brake rotor(s) replaced • Tire condition and pressure checked • Wheel(s) repaired • Wiring repaired
2025 Feb 3	219,989 KM	Service Facility	Vehicle serviced • Air filter checked • Air filter replaced • Cabin air filter replaced/cleaned • Differential cover resealed • Differential fluid flushed/changed • Oil and filter changed • Wiper(s) replaced

ODOMETER		SOURCE	DETAILS
2025 Jun 22	234,216 KM	Service Facility	Vehicle serviced • Air filter checked • Brakes checked • Brake rotor(s) resurfaced • Front brake pads replaced • Front brake rotor(s) replaced • Oil and filter changed • Rear brake pads replaced • Rear brake rotor(s) resurfaced • Wiper(s) replaced
2025 Nov 10	249,060 KM	Service Facility	Vehicle serviced • Antifreeze/coolant checked • Cabin air filter replaced/cleaned • Coolant reservoir replaced • Cooling system checked • Cooling system serviced • Oil and filter changed
2025 Dec 18	256,808 KM	Service Facility	Vehicle serviced • Antifreeze/coolant checked • Cooling system checked • Serpentine belt replaced • Thermostat replaced
2026 Jan 19	258,235 KM	Service Facility	Vehicle serviced • Engine serviced • Fluids checked • Headlight bulb(s) replaced • Starter overhauled/repared • Starter replaced • Transmission checked • Wiring repaired
2026 Feb 22	258,340 KM	Service Facility	Vehicle serviced
2026 Apr 22	69,495 KM	Service Facility	Vehicle serviced • Electrical system checked • Wiring repaired



Open Recalls

✓ No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact FORD or visit [Ford's website](https://www.ford.ca/support/recalls/). (https://www.ford.ca/support/recalls/)



Stolen Vehicle Check

✓ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2019 Nov 19		Krown Rust Control Burlington, Ontario, Canada	Service Record	Vehicle serviced
2019 Nov 22		Service Facility Canada	Service Record	Vehicle serviced
2019 Nov 25		Whiteoak Ford Lincoln Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2019 Nov 26		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Commercial Vehicle colour noted as black
2019 Dec 2		Whiteoak Ford Lincoln Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2020 Nov 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial Vehicle colour noted as black
2021 Sep 15	63,830 KM	Active Green & Ross Markham, Ontario, Canada	Service Record	Vehicle serviced
2021 Nov 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial Vehicle colour noted as black
2021 Dec 7	74,920 KM	Active Green & Ross Markham, Ontario, Canada	Service Record	Vehicle serviced
2022 Mar 14	85,609 KM	Active Green & Ross Markham, Ontario, Canada	Service Record	Vehicle serviced
2022 Jun 21	96,823 KM	Active Green & Ross Markham, Ontario, Canada	Service Record	Vehicle serviced
2022 Sep 26	109,386 KM	Jiffy Lube #1094 Burlington, Ontario, Canada	Service Record	Vehicle serviced
2022 Oct 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial Vehicle colour noted as black
2023 Jan 9	124,974 KM	Active Green & Ross Markham, Ontario, Canada	Service Record	Vehicle serviced
2023 Feb 9		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial Vehicle colour noted as black
2023 Mar 21	136,973 KM	Active Green & Ross Markham, Ontario, Canada	Service Record	Vehicle serviced
2023 Nov 22	170,813 KM	Active Green & Ross Markham, Ontario, Canada	Service Record	Vehicle serviced

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2024 Jan 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2024 Jul 17	194,808 KM	Active Green & Ross Markham, Ontario, Canada	Service Record	Vehicle serviced
2024 Sep 12	200,407 KM	Service Facility	Service Record	Vehicle serviced
2025 Feb 3	219,989 KM	Service Facility	Service Record	Vehicle serviced
2025 May 14		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2025 Jun 22	234,216 KM	Service Facility	Service Record	Vehicle serviced
2025 Oct 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2025 Nov 10	249,060 KM	Service Facility	Service Record	Vehicle serviced
2025 Dec 18	256,808 KM	Service Facility	Service Record	Vehicle serviced
2026 Jan 19	258,235 KM	Service Facility	Service Record	Vehicle serviced
2026 Feb 22	258,340 KM	Service Facility	Service Record	Vehicle serviced
2026 Apr 22	69,495 KM	Service Facility	Service Record	Vehicle serviced



Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2026 CARFAX Canada ULC. All rights reserved.

