



Vehicle History Report # 72553080
Report Date: September 8, 2026 | 12:15 p.m. EDT
Report Status: Complete

2018 NISSAN KICKS S

Hatchback | 4 Cylinders | Gas
3N1CP5CU5JL525776
Country of Assembly: Mexico
Last Reported Odometer: 96,025 KM

One Owner™ > No Reported Accidents™ >



No Accident/Damage Records Found



Last Registered In:
Ontario (Normal)



17 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import/Export Records Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of September 08, 2026 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

There are no accidents/damage reported on this vehicle.



Registration

This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2018 Sep 12		Burlington Nissan Burlington, Ontario, Canada	Vehicle serviced - Pre-delivery inspection completed - Nitrogen fill tires
2018 Nov 10	1,802 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Vehicle serviced - Tire repaired - Tire(s) replaced
2019 May 6	8,187 KM	Burlington Nissan Burlington, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Oil and filter changed
2019 May 11	8,383 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Tires rotated
2019 Oct 3	16,699 KM	Burlington Nissan Burlington, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tires rotated
2019 Nov 30	19,512 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Tires rotated
2021 Jul 3	35,740 KM	Jiffy Lube Hamilton, Ontario, Canada	Vehicle serviced Oil and filter changed
2022 Aug 5	46,755 KM	Jiffy Lube Hamilton, Ontario, Canada	Vehicle serviced Oil and filter changed
2023 Apr 6	54,634 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Vehicle serviced - Maintenance inspection completed - Brakes serviced

3N1CP5CU5JL525776

ODOMETER		SOURCE	DETAILS
			• Front brake pads replaced • Front brake rotor(s) replaced • Tires rotated
2023 Aug 12	59,526 KM	Jiffy Lube Hamilton, Ontario, Canada	Vehicle serviced • Cabin air filter replaced/cleaned • Oil and filter changed
2023 Dec 15	62,970 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Vehicle serviced • Maintenance inspection completed • Tires rotated
2024 Jun 17	68,600 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Vehicle serviced • Maintenance inspection completed • Air filter replaced • Oil and filter changed • Tires rotated
2024 Dec 19	77,168 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Vehicle serviced • Maintenance inspection completed • Four wheel alignment performed • Front strut(s) replaced • Oil and filter changed • Tires rotated
2025 May 21	82,468 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Vehicle serviced • Maintenance inspection completed • Tires rotated
2025 Nov 6	89,006 KM	Jiffy Lube Hamilton, Ontario, Canada	Vehicle serviced • Oil and filter changed
2025 Nov 20	89,571 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Vehicle serviced • Maintenance inspection completed • Brakes checked • Brake fluid flushed/changed • Front brake caliper(s) replaced • Front brake pads replaced • Front brake rotor(s) replaced • Tires rotated
2026 Jun 15	96,025 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Vehicle serviced • Maintenance inspection completed • Tires rotated



Open Recalls

Recall #: R1911 | VSRC 19 2018-19 REAR VISIBILITY SYSTEM UPDATE Recall Date: 2019 May 15

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact NISSAN or visit [Nissan's website](https://www.nissanusa.com/recalls-vin.html). (https://www.nissanusa.com/recalls-vin.html)



Stolen Vehicle Check

✓ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2018 Sep 12		Burlington Nissan Burlington, Ontario, Canada	Service Record	Vehicle serviced
2018 Oct 2		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Vehicle colour noted as white
2018 Nov 10	1,802 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Service Record	Vehicle serviced
2019 May 6	8,187 KM	Burlington Nissan Burlington, Ontario, Canada	Service Record	Vehicle serviced
2019 May 11	8,383 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Service Record	Vehicle serviced
2019 May 15		NISSAN	Recall	Manufacturer Recall Issued Recall # R1911
2019 Oct 3	16,699 KM	Burlington Nissan Burlington, Ontario, Canada	Service Record	Vehicle serviced
2019 Nov 30	19,512 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Service Record	Vehicle serviced
2020 Jul 9		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2021 Jul 3	35,740 KM	Jiffy Lube Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2022 Aug 5	46,755 KM	Jiffy Lube Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2023 Apr 6	54,634 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Service Record	Vehicle serviced
2023 Aug 12	59,526 KM	Jiffy Lube Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2023 Dec 15	62,970 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Service Record	Vehicle serviced

3N1CP5CU5JL525776

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2024 Jun 17	68,600 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Service Record	Vehicle serviced
2024 Dec 19	77,168 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Service Record	Vehicle serviced
2025 May 21	82,468 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Service Record	Vehicle serviced
2025 Nov 6	89,006 KM	Jiffy Lube Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2025 Nov 20	89,571 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Service Record	Vehicle serviced
2026 Jun 15	96,025 KM	Active Green & Ross - Burlington Burlington, Ontario, Canada	Service Record	Vehicle serviced



Questions? We're here to help.
Visit us at support.carfax.ca

CARFAX Canada One Owner™ Badge
The CARFAX Canada One Owner™ badge that is based on the registration information reported to CARFAX Canada. The badge is available for personal and commercial vehicles that have only been registered in the provinces of British Columbia, Alberta, Saskatchewan, Manitoba, Ontario, Quebec, Nova Scotia, New Brunswick, or PEI.

CARFAX Canada No Reported Accidents™ Badge
The CARFAX Canada No Reported Accidents™ badge is based on the damage records and/or branding information reported to CARFAX Canada. The badge is available for personal vehicles that have only been registered in Canada, and were not, at the time this report was generated, declared stolen.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

