



Vehicle History Report #: 68947906
Report Date: April 10, 2026 | 4:26 p.m. EDT
Report Status: Complete

2016 VOLKSWAGEN PASSAT SE

Sedan | 4 Cylinders | Gas

1VWBS7A35GC040049

Country of Assembly: United States

Last Reported Odometer: 33,218 KM



Accident/Damage Records Found



Last Registered In:
Ontario (Normal)



4 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import/Export Records Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of April 10, 2026 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
2017 Jan 29	Ontario, Canada	
	Claim: Collision	\$2,020.00

Other Damage Records

RECORD DATE	DETAILS	AMOUNT
2017 Jun 19	Ontario, Canada	
	Glass Record	\$121.00
2018 May 25	Ontario, Canada	
	Glass Record	\$233.00



Registration

This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: *Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.*



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2016 Apr 4		Volkswagen MidTown Toronto Toronto, Ontario, Canada	Vehicle serviced Pre-delivery inspection completed
2016 Oct 11		Krown Oshawa Oshawa, Ontario, Canada	Vehicle serviced Undercoating/rustproofing applied
2017 Oct 21		Krown Oshawa Oshawa, Ontario, Canada	Vehicle serviced Undercoating/rustproofing applied
2018 Apr 20	33,218 KM	STE Auto Centre Whitby, Ontario, Canada	Vehicle serviced

Open Recalls

Recall #: 94L9 | HEADLAMP CAPS Recall Date: 2019 Jun 11

Recall Description

The headlights are not permitted to have a horizontal adjustment for vehicles certified according to regulatory requirements. The horizontal adjuster is blocked from further adjustment by means of a cap (after the initial adjustment is performed in the production process). Some vehicles did not have the required cap installed. Incorrectly adjusted headlights may result in reduced visibility (for the driver and other motorists) which could increase the risk of a crash.

Remedy

Inspect and, if necessary install missing headlight adjusting screw caps.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit [Volkswagen's website](https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html). (https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html)

Stolen Vehicle Check

✔ This vehicle is not actively declared stolen.

Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2016 Apr 4		Volkswagen MidTown Toronto Toronto, Ontario, Canada	Service Record	Vehicle serviced
2016 May 16		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Vehicle colour noted as gray
2016 Oct 2		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2016 Oct 11		Krown Oshawa Oshawa, Ontario, Canada	Service Record	Vehicle serviced
2017 Jan 29		Ontario, Canada	Collision	
2017 Jun 19		Insurance Records Ontario, Canada	Glass Record	\$121.00
2017 Oct 21		Krown Oshawa Oshawa, Ontario, Canada	Service Record	Vehicle serviced

1VWBS7A355GC040049

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2018 Apr 20	33,218 KM	STE Auto Centre Whitby, Ontario, Canada	Service Record	Vehicle serviced
2018 May 25		Insurance Records Ontario, Canada	Glass Record	\$233.00
2018 Nov 5		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal Vehicle colour noted as gray
2019 Jun 11		VOLKSWAGEN	Recall	Manufacturer Recall Issued Recall # 94L9
2022 Sep 9		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as gray
2024 Aug 26		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2025 Aug 26		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2026 Mar 18		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as gray
2026 Mar 27		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as gray



Questions? We're here to help.
Visit us at support.carfax.ca

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

1VWB57A35GC040049